

# PERFORMANCE RESULTS EXAMPLE

## Food & Beverage Industry (Netherlands)

→ Condenser in milk factory

Tube Size	40 mm ID (1,575")
Tube length	5 m
# of Tubes	484
Inspection Time	½ shift including setup
Defects Found	16 tubes with multiple holes

### Outcome

→ Tubes with holes were plugged and condenser very fast back in operation

